

GAS-TRAK ONLINE

HOW TO EDIT CYLINDER WEIGHTS IN CYLINDER TRACKING



Your Cylinder Tracking, Reporting and Stock Management Solution.



HOW TO EDIT CYLINDERS WEIGHT IN CYLINDER TRACKING

How to edit cylinder's weight.

- 1. How to edit a refrigerant cylinder's weight.
- 2. Click on **Cylinder Stock**.



3. Click on the cylinder you wish to edit.



4. Click on **Edit weight.**



		09:11 🖬 🖻 🤁		in © ∦
		Cylinder	Stock	+ -
	Sa	rah	*	ଦ ? ଟ
	S	ARAH		
		AM021354		
		AM021354		
<		Edit Weight		
		Return - Stock	κ.	
		Return - Whol	esaler	
	I	Sell		
			Cancel	
		LM11112222 (0/12) Rental Cost = 5 Contains:		
			0	<

5. Click on **select**.

09:11 🖾 🖻 🔮		🕷 🕾 al 🗎
← Edit W	eight	•
Sarah		* C
AM021354 HF01233ZD (12	2/12)	
Product HF0123	33ZD	Q
Recover/Chage	Select	
Weight (kg)		5
Reference		
111	0	<

6. Click on charge.



	08:13 ⊠ ← Edit W	/eight	× 🤋 🖬
-	Sarah		* 2
	LM456789 R407F (10/12)		
Pr	Select		
Re	Recover		
Re	Charge)	
		Cancel	
		0	<

- 7. Enter how many kilos you have taken out of the cylinder.
- 8. Click Done.





9. Click on reference and write in any relevant details

10. Click on **Done**.

08:15 🖼		* 🗟 🚛
Sarah	â	e
LM456789 R407F (10/12)		
Product R407F		Q
Recover/Charge Charge	ge	
Weight (kg)	02	
Reference		
(t) 😧 😨	GIF 🦊	¢*
1 2 3 4 5	6 7 8	390
q w e r t	y u	i o p
a s d f	g h j	k I
↑ z x c	v b n	m 💌
!#1 , Engi	ish (UK)	. Done
Ш	0	~

11. Click Save.



^{09:44} ← Edit We	ight	
Sarah	1	* <mark>2!</mark>
LM456789 R407F (10/12)		
Product R407F		Q
Recover/Charge Cl	narge	
Weight (kg)	2	
Reference	reference	р^
111	Ο	<
	0	

How to edit a recovery or receiver cylinder's weight.

- 1. Click on **Cylinder Stock**.



2. Click on the cylinder you wish to edit

Ringtone	er Stock	
Sarah	*	Q ? S
SARAH		
AM021354 HF01233ZD (10 No Rental Data Contains: HF012 Purity (Min) = 0	/12) 233ZD	1
LM00000000 (0/2) No Rental Data Contains: Purity (Min) = 10	10 %	
LM098767 (0/0) Rental Cost = 20 Contains: Purity (Min) = 10))0 %	
LM098780 R404A (-12/3) No Rental Data Contains: R404A Purity (Min) = 0	A	
LM11112222 (0/12) Rental Cost = 5 Contains:		
111	0	<

3. Click on Edit weight.

09:12 🖬 🖻 🕅		🗎 الد 🕫 🎽			
← Cylindei	r Stock	+ -			
Sarah	*	२ २ छ			
SARAH					
LM000000	00				
Edit Weight					
Return - Stoc	Return - Stock				
Return - Wholesaler					
Sell					
Transfer					
	Cancel				
No Rental Data Contains: R404A Purity (Min) = 0 LM11112222					
(0/12) Rental Cost = 5 Contains:					
	0	<			

4. Click on the looking up glass by product.

-



09:13 🖾 🖻 🕏 ← Edit Weight	•	k ®.∥ ∎ ■
Sarah	*	S
LM00000000 (0/2)		
Product Select		Q
Recover/Charge Select		
Weight (kg)	0	
Reference		

5. Click on the magnifying glass in the top right-hand corner and type in the type of product and click on it.



6. Click on Select



09:13 🖬 🖻 🕏 ← Edit Weight	¥ ®.d ii ■
Sarah	* 2
LM00000000 (0/2)	
Product R134A	Q
Recover/Charge Select.	>
Weight (kg)	0
Reference	
III C) <

7. Click on **Recover**



8. Click on the 0 and enter the weight of the product you have put into the recovery bottle.



09:13 🖬 🖻 🕏 ← Edit Weigh	t Sali
Sarah	* 2
LM00000000 (0/2)	
Product R134A	Q
Recover/Charge Recov	er
Weight (kg)	0
PurityLabel (%)	0
Reference	
111 (

9. Click on done

09:13 🖼 🖡	× 0		💐 🗟 all 📋	
← Ed	it Weight	t	•	
Sarah		ñ	S	
LM000 (0/2)	00000			
Product R1	34A		Q	
Recover/Char	ge Recov	er		
Weight (kg)		6		
PurityLabel (%	b)	0		
1	2	3	×	
4	5	6	Done	D
7	8	9		ſ
	0			
Ш	(D	~	

- 10. Click on reference and write in any relevant details.
- 11. Click on **Done**.



08:50 🖬 👋 🍕 🛄 💼
Sarah 🔗 🔁
LM0000000 (0/10)
Product R134A
Recover/Charge Select
Weight (kg) 6
Reference
(ҧ) 🕹 🥵 🚥 🌷 🗳 …*
1 2 3 4 5 6 7 8 9 0
q w e r t y u i o p
asdfghjkl
★ z x c v b n m
!#1 , English (UK) . Done
III O Y

12. Click on Save.

08:51 🖼		¥ 🖘 🛯 🛔
← Edit	Weight	
Sarah	6	8
LM00000	00	
Product R134	A	Q
Recover/Charge Select		
Weight (kg)	6	
Reference	reference	
111	Ο	<



YOUR GAS-TRAK ONLINE SUPPORT TEAM:

Phone: +44 (0) 1275 376600 Email: support@gastrakonline.com Web: www.gastrakonline.com



Your Cylinder Tracking, Reporting and Stock Management Solution.

